



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

ENGINEERING CHANGE REQUEST

ECR 16

Date Opened:	8/3/20 11:34 PM	Requested By:	Becker, Jacob
Type:	Drawing/Pattern Change	Requester*:	Black, Ross
Priority:	Critical	DE Approver*:	Gardiner, Jason
Status:	Quality Disposition	Program Manager:	Lee, Michael
Reason:	Wiper deflector needs to be reflected in BOM for 7306 & 7308. F/N 90 should be: 601.2991	Responsible Engineer:	Becker, Jacob
Expense:	1000	ECR Lead*:	Becker, Jacob
Target Date:			
Execution Date:			
ECR Approval No:			
RE (R&D):		**BRIEF DESCRIPTION**:	647.7300 F, EC135 Cable Cutters Kit, Incorrect BOM callout
Status Note:		DESCRIPTION/ ADR CONTENT**:	Wiper deflector is incorrectly indicated in 7305 fixed provisions. F/N 90 Rivet shows incorrect P/N 601.xxxx

CUSTOMER APPROVALS

Customer	Customer Visible	Customer Approval Required	*	Customer Approved
----------	------------------	----------------------------	---	-------------------

PARTS

Part No	Rev	Part Status	Name	Type	Customer Part	Special Comments	Documents
647.7305		On hold	EC135 T2/P2/T3/P3 Fixed Provisions Compatible with Cable Cutters	Finished Good	647.7305 647.7305 647.7305		
647.7306		On hold	EC135 T2/P2 Cable Cutters (Removable Provisions Only)	Finished Good	647.7306 647.7306 647.7306 647.7306 647.7306 647.7306		
647.7308		On hold	EC135 T3/P3 Cable Cutters (Removable Provisions Only)	Finished Good	647.7308		

INVENTORY DISPOSITION

Part No Revision	Material No	Current Inventory Qty	Purchasing On-Order Qty	Qty Scheduled for Production
647.7305		0 *	0 *	0 *
647.7306		0 *	0 *	0 *
647.7308		1 Quarantine	0 *	0 *

EFFECTS

Effect Group	Effects
1. Quarantine?	Immediate quarantine required (quarantine all stock)
2. ECR Lead Assessment - Impacted Docs & Output	Drawing Change Required, Update/Create IIN (update II to reflect that parts are now in removables), Update/Create ICA (update ICA to reflect that parts are now in removables)
3. ECR Lead Assessment - Status	UR - Full Under Review (parts on hold)
4. Production Type	In-house production
5A. ECR Lead Assessment - MINOR Changes VISTA	Correction of drawing errors (wiper deflector in wrong config), Typographical errors (typo in f/n 90)